

Oil Field Environmental Incident Summary

Incident: 20160523162511 **Date/Time of Notice:** 05/23/2016 16:25

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: ANTONSON 01-12-163-95H

Field Name: FORTHUN

Well File #: 18941

Date Incident: 5/22/2016

Time Incident: 07:37

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 95

Sec: 1

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Ben Tarap
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		
Brine	4	Barrels	4	Barrels		

Other

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

All visibly contaminated material removed and replaced with clean-fill.

Wastes Disposal Location: 13 Mile Disposal

Agencies Involved: Called John Rumppe on 5/23/2016 @ 4:20 pm

Updates

Date: 5/23/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, was contained within the diking according to the report. NDIC retains oversight.

Date: 6/6/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.